

Change Notice

MR & MRB Series

Changes to Location & Production for MRB & MRT Rotaries

Type of Change:

- Engineering Part Number
- Product Appearance

1. The location of production will change for MRB and MRT Rotaries from the Japan factory to the Philippines factory. The place of manufacture will no longer appear on the bottom of switches, and the lot number on the switch will have a dot mark above the second digit. The box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." All of these modifications will apply to standard and custom products.



Changes for MRB & MRT Rotaries

	Identification	Lot Number	Shipping Box
Before Changes	"JAPAN" On Case for MRB On Identification Plate for MRT	Example of Lot Number 69	<p>"JAPAN FACTORY" printed on side of box</p>
After Changes	"JAPAN" Removed	Example of Lot Number with Dot Mark Above Second Digit 6[•]9	<p>"PHILIPPINES FACTORY" printed on side of box</p>

Notes

There are no changes to the switches' dimensions or specifications.
The location of the Lot Number on switch may vary depending on the part number.
Contact the factory if more details are needed.

MR Rotaries Affected by Location & Production Changes			
MRB12B	MRB12H	MRB14B	MRB14H
MRB22B	MRB22H	MRB24B	MRB24H
MRT22	MRT23	---	---

Effective Date

Changes to MRB and MRT Rotaries will be effective September 2017.

NKK SWITCHES CO., LTD. <http://www.nkk.com> E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

Change Notice

MR Series

Addition of New Logo & UL Factory Code for MRT Rotaries

Type of Change:

- Engineering Part Number
- Product Appearance



2 MRT Rotaries will have a change on the switch case that will include both standard and custom devices. The updated logo will replace the factory name "NIKKAI". The table illustrates the difference.

Changes for MRT Rotaries

	Before Changes	After Changes
Identification on Switch	Factory Name NIKKAI	Updated Logo

MRT Rotaries with New Identification	
MRT22	MRT23

3. MRT Rotaries with UL approval will have a change on the switch case to include both standard and custom devices. Previously, the UL symbol appeared on the case without a factory code. After the change, the code 080 will appear next to the UL symbol. The table illustrates the difference.

UL Factory Code Change	
Before Change	After Change
UL Approval & No Factory Code 	UL Approval & Factory Code Added

MRT Rotaries with New UL Factory Code	
MRT22/U	MRT23/U

Notes

There are no changes to the switches' dimensions or specifications in relation to the above revisions. The location of the UL code on switch may vary depending on the part number. Contact the factory if more details are needed.

Effective Date

Changes to MRT Rotaries will be effective September 2017.

NIKK SWITCHES CO., LTD. <http://www.nkk.com> E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031